



Department of Energy
National Nuclear Security Administration
 Washington, DC 20585

RECEIVED
 00 SEP -6 PM 3:42
 DNF SAFETY BOARD

September 1, 2000

The Honorable John T. Conway
 Chairman
 Defense Nuclear Facilities Safety Board
 625 Indiana Avenue, N.W., Suite 700
 Washington, D.C. 20004

Dear Mr. Chairman:

The Secretary's Action Plan, in response to the Board's DNFSB/TECH-23, made a commitment in Deliverable 3.2 to issue a revision to The Department of Energy Handbook (DOE-HDBK-3010-94), *Airborne Release Fractions/Rates and Respirable Fractions for Nonreactor Nuclear Facilities*, by September 1, 2000.

A Change Notice was issued on March 1, 2000 for DOE-HDBK-3010-94. The first paragraph of Volume 1, Section 5.4.1, on Page 5-30 was deleted. The PDF version of the Handbook currently in the DOE Technical Standards home page has been updated incorporating the Change Notice. A copy of the Change Notice is attached for information.

If you have any questions, please call me at (202) 586-2179; or have your staff call Richard Crowe at (301) 903-6214.


Sincerely,

Madelyn R. Creedon
 Deputy Administrator
 for Defense Programs

Attachments



RECEIVED
00 SEP -6 PM 3:42
DNF SAFETY BOARD



NOT MEASUREMENT
SENSITIVE

DOE-HDBK-3010-94
December 1994

CHANGE NOTICE NO. 1
March 2000

DOE HANDBOOK

AIRBORNE RELEASE FRACTIONS/RATES AND RESPIRABLE FRACTIONS FOR NONREACTOR NUCLEAR FACILITIES

Volume I - Analysis of Experimental Data



U.S. Department of Energy
Washington, D.C. 20585

AREA SAFT

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

This document has been reproduced from the best available copy.

Available to DOE and DOE contractors from ES&H Technical Information Services, U.S. Department of Energy, (800) 473-4375, fax: (301) 903-9823.

Available to the public from the U.S. Department of Commerce, Technology Administration, National Technical Information Service, Springfield, VA 22161; (703) 605-6000.

*Airborne Release Fractions/Rates and Respirable Fractions
For Nonreactor Nuclear Facilities*

Page / Section	Change
p. 5-30, Section 5.4.1	Delete the first paragraph of this section since it contains erroneous information.

5.4 HEPA FILTERS

5.4.1 Thermal Stress

HEPA filters, both unused and removed from service due to high differential pressures (clogged), were tested using solid particles at a range of temperatures less than required for failure. The efficiencies of the filters prior to testing for 1.8 μm particles ranged from 99.97% to 99.9999989%. Two high flow (2000 cfm) and one 1000 cfm HEPA filters with glass fiber media and various sealant and gasket materials were tested. No releases were found at temperatures below 150°C (175°C for one of the high flow filters). For the 1000 cfm type filter, the release rates for temperatures from 175°C and 190°C started at 1E-6/min and reduced to 5E-8/min within 1 hour (the lower limit of detection was 2E-8/min). The high flow HEPAs were tested to temperatures of 200°C and 250°C with release rates starting at 2E-4/min and 2E-5/min and reducing to 3E-7/min in 30 min and 2E-8/min in 60 min. The decay in release was exponential during the initial 30-minutes approaching the 60-min rate asymptotically. There was no release of contamination from a oven-fired, mineral sealant, high flow type filter at temperatures up to 350°C and the release in other types of HEPA filters is associated with the emission of smoke (binder, degradation of inert dust on filter, pyrolysis of gaskets). Thus, it appears that the heat-induced release from 1000 cfm HEPA filter prior to failure may be as high as 1E-5. It is assumed that HEPA filters destroyed by flame intrusion or by the impact of air at a temperature sufficiently high to melt the glass fiber are subjected to high temperature air to result in the release given above for heat-induced release. The RF is assumed to be 1.0 without an experimental basis. ARFs for high-flowrate HEPA filter may be an order of magnitude higher (1E-4). On these bases, bounding ARF and RF values for the impact of heat upon loaded HEPA filters are assessed to be 1E-4 and 1.0.

DNF SAFETY BOARD
00 SEP -6 PM 3:43
RECEIVED