



## Department of Energy

Richland Operations Office  
P.O. Box 550  
Richland, Washington 99352

DEC 5 1995

95-TSD-139

Mr. John T. Conway, Chairman  
Defense Nuclear Facilities Safety Board  
625 Indiana Avenue, N.W., Suite 700  
Washington, D. C. 20004

Dear Mr. Conway:

TRANSMITTAL OF U.S. DEPARTMENT OF ENERGY, RICHLAND OPERATIONS OFFICE (RL),  
QUARTERLY REPORT FOR DEFENSE NUCLEAR FACILITIES SAFETY BOARD (DNFSB)  
RECOMMENDATION 90-7, PERIOD JULY 1, 1995 THROUGH SEPTEMBER 30, 1995


Enclosed for your information are five copies of the eighteenth quarterly  
status report for the Program Plan responding to Recommendation 90-7 of the  
DNFSB. This status report covers the period from July 1, 1995 through  
September 30, 1995.

Quarterly progress is reported against the program activities described in the  
"Program Plan for Evaluation of the Ferrocyanide Waste Tank Safety Issue,"  
that address the six recommendations of 90-7. The status of milestones is  
reported against the schedule provided in the Program Plan.

We appreciate your continued interest and support in the resolution of all the  
Hanford radioactive waste tank safety issues.

If you have any questions, please contact me or your staff may contact  
Mr. Jackson E. Kinzer, Assistant Manager, Tank Waste Remediation System on  
(509) 376-7591.

Sincerely,

  
John D. Wagoner  
Manager

TSD:WFH

Enclosure

cc w/encl:  
R. Guimond, EM-2  
J. C. Tseng, EM-30  
M. B. Whitaker, EH-9  
M. A. Hunemuller, EM-30  
S. L. Trine, RL DNFSB Liaison